



Technical Bulletin n°3

17th July, 2009

Reference: FR20_BT_2009_03_UK
Date: 17th July, 2009
Subject: Push-pull cable default
Parts: Push-pull cable

A production problem in 2 batches of push pull cable (Ref 77 11 154 263) has been detected. This concerns cables with the reference **"08/09"** or **"09/09"** written in white on the cable casing.

A crimping problem might appear after a few kilometres on some cables with these references, as shown below:



If you have such cables, check with your local Renault Sport spare parts dealer to arrange the exchange.

Otherwise, this exchange is also possible at the Renault Sport Spare parts truck for those who are participating in the Eurocup Formula Renault 2.0 in Le Mans this week end.